Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
Li	16	"318"/\$.ccls. and switching and transistor and power adj steering and regulator	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 13:14
L2	1	(semiconductor adj switching and PWM and driving and circuit and overheat and driving).CLM.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 13:16
L3	29	"318"/\$.ccls. and (overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 13:17
L4	47	"318"/\$.ccls. and (overload or overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 13:24
L5	141	(overload or overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:00
L6	4	318/138.ccls. and (overload or overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:00
L7	9	318/254.ccls. and (overload or overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:01
L8	3	318/439.ccls. and (overload or overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:01

L9	0	318/700.ccls. and (overload or	US-PGPUB;	OR	OFF	2005/11/21 14:01
		overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB			
L10	9	318/432-434.ccls. and (overload or overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:01
L11	1	318/471-477.ccls. and (overload or overheat or overcurrent) adj (sensor or detect or detection) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:02
L12	23	318/471-477.ccls. and (overload or overheat or overcurrent) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:03
L13	79	318/432-434.ccls. and (overload or overheat or overcurrent) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:03
L14	29	388/800-811.ccls. and (overload or overheat or overcurrent) and PWM and motor	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2005/11/21 14:03